



## 2410169 G-0600/G-0800 CONTACTOR RELOCATION Installation Instructions

Procedure:

1. Disconnect power supply to ice machine.
2. Remove old contactor.
3. **IMPORTANT:** The replacement contactor is to be mounted on the component box bottom in an upright position using the clips and Mylar enclosed (do not remount contactor in its original side position).

**CAUTION:** Mylar must be installed to prevent electrical arcing to metal surfaces.

